








Eddystone 1004A Pre-restoration photos by Glenn Little, WB4UIV



Glenn obtained this 1004A a few years ago from an estate auction and it is badged as a Marconi Sentinel. Glenn was enquiring about differences between the 1004 and 1004A and we realised we had very little information on the website about the 1004A. It looks as if the main difference is the lack switched crystal oscillators. Glenn can see that the components are missing from the board. Marconi Marine designated this as a reserve receiver (ie to back up the main receiver in case of a fault). The last time Eddystone made any of these for Marconi Marine was in 1984. This might be from that batch. Glenn will be doing some restoration work on the set and we will keep you informed of his progress











RESERVE RECEIVER
IDENTITY EC 1004A SER NO. 1219
MADE IN ENGLAND
THE M.I.M. CO. LTD. CHELMSFORD.

1	3	5	7	9	11	13	15	17	19	21	23
2	4	6	8	10	12	14	16	18	20	22	24
A	B	C	D	E	F	G	H	J	K	L	M



TYPE 1004A

SER. NO. 2013

PLEASE QUOTE ABOVE NUMBERS
IN ALL CORRESPONDENCE

MANUFACTURED BY

EDDYSTONE RADIO LTD.

BIRMINGHAM B31 3PP · ENGLAND