



EDDYSTONE USER GROUP

BI-MONTHLY NEWSLETTERS / 'LIGHTHOUSE' 1 - 96

INDEX TO EDDYSTONE MODELS

Viewers should note that this index is not necessarily 100% complete or accurate. Any omissions or corrections should be e-mailed for updating to Anthony Richards, GW4RYK, at forwyn@aol.com

Some of the earlier radios, such as the Atlantic Three, are not factory built sets but use Eddystone circuitry and 'Eddystone Specified' components and were featured in the 'Eddystone Short Wave Manuals'; thus they are included here for the sake of completeness.

Marconi & MIMCO radios are cross-referenced and can be found collectively under 'M'.

When looking at faults and problems, viewers are reminded that many radios shared common circuitry and components, for example the EB35, EB36, EB37 & EC10 range, and the 840 range. Whilst faults etc. with individual models are listed as they arise in the newsletters, much can be gleaned from looking at references to similar sets.

	<i>issue</i>	<i>page</i>
31A		
brief description	46	6
catalogue extract	49	9
comparison tests, used in.....	71	40
eBay	89	18
featured receiver	32	29
manual	19	11
P.O. versions.....	57	10
query as to existence of Model 31	58	17
40A		
brief description	5	1
eBay	88	24
mains psu danger.....	25	7
narrow band filters, query as to.....	37	24
scale plate photocopy.....	67	3
ssb mod	67	9
used by Ted Moore	82	18
on EUG net	88	18
brief description	7	2
160		
services equivalent of ECR	21	9
214/215		
advert, Stratton & Co.....	79	49
brief description	24	9
.....	36	13
.....	52	6

214/215 (cont)

.....	53.....	11
.....	38.....	25
development.....	70.....	48
RAF, used by, plus brief details	88.....	17
358		
blueprint register.....	80.....	28
acquired at car boot sale	51.....	23
Graeme Wormald.....	43.....	6
advert 1942.....	3.....	7
.....	21.....	5
Webbs' Radio.....	43.....	12
.....	73.....	20
.....	61.....	16
.....	86.....	36
Australia, use in.....	29.....	29
comparison with 400	71.....	16
condensers, paper.....	37.....	8
crystal, dud	39.....	20
dates when current.....	23.....	17
.....	59.....	7
development model found.....	65.....	37
drifting, cure	44.....	15
EB34 diode valves, replacement with 1N914 diodes.....	42.....	20
early & late sets, differences	48.....	22
electric shock.....	4.....	5
fault cured	88.....	20
filters, crystal	42.....	20
Gulf War, monitoring of	8.....	1
HMS Collingwood, aboard.....	86.....	10
i.f. transformer repair.....	64.....	61
mechanical problems	40.....	18
motorboating	7.....	5
'new' set discovered	66.....	5
.....	66.....	10
Norway, in use on WWII trawler.....	8.....	16
overhaul	10.....	17
.....	10.....	22
repairs	49.....	17
.....	63.....	14
rescued from burial (Dave Langdon).....	21.....	10
RAF		
usage proven	87.....	30
mystery photo.....	70.....	53
Royal Navy		
designation B34	42.....	10
in use with	71.....	44
restoration	55.....	1
.....	71.....	11
query as to modifications	57.....	10
S meter sticking.....	12.....	14
Used at Admiralty Signal Establishment	82.....	6
unwanted emissions.....	92.....	32
valves		
ECC82 replacing EF39	25.....	15
output	35.....	23
.....	49.....	31
vhf coils	14.....	7
.....	21.....	9
Wireless for the Warrior, included in	89.....	36
400, comparison with	71.....	16
400/440/450		
acquired by Ted Moore	96.....	39
advert	55.....	38
Webb's Radio (1941)	82.....	23

400/440/450 (cont)

	61.....	16
amateur use, postwar, 4 metre band	85.....	10
analysis of (Peter lankshear).....	71.....	37
brief description	12.....	24
.....	18.....	10
.....	24.....	10
.....	29.....	11
.....	31.....	22
.....	36.....	7
.....	52.....	6
.....	53.....	11
comments on usage of, Pat Hawker	72.....	47
.....	73.....	22
comparison with 358	71.....	16
components used, quality of.....	85.....	7
D Day, used in invasion.....	73.....	25
.....	80.....	29
description	71.....	36
ditto, Graeme Wormald	73.....	23
eBay	86.....	13
Home office MF network	73.....	29
i.f. frequency.....	72.....	15
Lancashire Police, used by	77.....	8
query as to Air Sea Rescue use	73.....	6
recomissioning by member	65.....	6
S147, Admiralty nomenclature for 440/450.....	76.....	15
valves, ECC82 replacing EF39	25.....	15
Wireless World, write-up in (S400).....	74.....	12
358, comparison with	71.....	16
504		
acquired		
Ted Moore, with strange valve	94.....	47
acquired by member	16.....	3
advert		
.....	53.....	9
factory	67.....	24
N.Z.	18.....	5
a.f. gain, fault.....	10.....	14
alignment frequencies	4.....	3
avc fault	10.....	14
brief description	29.....	11
drifting	58.....	34
curing	40.....	5
eBay	87.....	12
.....	90.....	17
featured receiver	21.....	3
introduced 1946.....	68.....	4
mains switch problem.....	95.....	20
rejuvenation of.....	32.....	14
.....	39.....	14
S meter, zeroing problems	42.....	17
scale plate, photocopy available	44.....	27
story of one receiver, Peter le Quesne.....	74.....	4
values of, current.....	44.....	9
valves, ECC82 replacing EF39	25.....	15
556/B psu	20.....	9
556		
alignment frequencies	4.....	3
brief details and picture	96.....	37
comparison with 504	15.....	1
comments on (ted Moore)	89.....	28
fuse, lack of	78.....	14
mains transformer replacement	78.....	14
pot. replacement.....	78.....	14

556 (cont)

resistors, high	86	22
second receiver found (Ted Moore)	78	16
/B		
solid state vibrator	60	4
640		
acquisition & renovation	63	7
.....	70	32
.....	72	10
advert	6	12
.....	9	23
.....	27	32
.....	33	11
.....	42	27
.....	53	9
Arnold & Wright, N.Z.	37	26
1948 (Webb's Radio)	76	55
a.f. gain causing howl.....	19	2
agc not working	6	9
alignment frequencies	4	3
amateur use, 1950	55	35
audio output		
distorted	17	6
.....	52	2
lack of.....	6	9
.....	9	9
bandspread, not working.....	12	2
bfo		
improvement	66	6
.....	74	19
rustling noise at zero beat.....	10	9
.....	29	17
components, need changing in most sets.....	10	13
cooling, improving	59	5
crystal		
phasing, reversed to eliminate QRM.....	31	2
filter switch	62	9
drifting	34	21
double superhet modified set	55	26
drive cord joy	95	19
electrolytics	3	2
.....	34	8
faults, common	6	9
.....	33	19
fault cured, dry joint	80	29
.....	80	31
featured receiver	6	2
FETs, use of.....	57	6
frequency jumping	34	29
fuse, ht, fitting of	34	20
handles, chrome.....	3	2
.....	49	27
headphones, use of modern type.....	48	25
heat reduction.....	72	19
hum	3	2
.....	11	4
.....	33	22
i.f. breakthrough	27	14
.....	39	7
.....	67	10
in use (Peter Stein).....	27	16
loudspeaker, fitting of	33	23
MIMCO version (not ?).....	55	20

640 (cont)

modifications, factory, early models	10	24
.....	31	8
motorboating	10	14
.....	25	16
noise limiter, fault	6	9
.....	12	14
.....	61	11
obituary (b. 1948, d. 2004)	88	46
ocean voyage, used on (1952).....	55	26
output stage	8	6
fault	27	25
overheating	8	2
.....	12	14
performance, poor, advice sought.....	61	33
pre-production models, on trial.....	17	3
presented to RSGB	16	2
.....	93	7
prices, new	11	17
product detector, fitting.....	29	19
problems with set	53	19
QRP transmitter, within	11	3
.....	13	4
.....	15	21
.....	75	9
rectifier, OZ40, use of.....	28	17
renovation	32	13
from scrap (James Scott).....	18	19
and usage	18	7
repairs to	75	10
.....	86	42
resistor		
failure	70	16
upgrading	25	7
r.f. gain pot, use of correct type.....	36	2
rf stage, cascade conversion.....	76	18
S meter	4	2
.....	6	9
serial nos., query as to early	58	18
speaker, query as to internal.....	50	3
testimonial		
Abu Sueir	59	24
Calcutta.....	57	34
tracking, curing.....	66	4
tuning		
dial, slippage	24	1
gang, cleaning.....	55	13
jump in, curing.....	65	34
comments on	61	34
mechanism, description & maintenance	43	9
.....	46	4
usage under modern conditions	46	22
valves		
6V6	74	10
ECC82 replacing EF39	25	15
failure	70	16
metal, shock warning	31	17
miniature, fitting.....	30	18
mixer	34	26
.....	56	4
revalving.....	67	7
vhf (2 meters) modification	53	6
1948 station recreation, use in	27	9

640A	blueprint found	94	49
659	advert, factory	9	22
		42	27
	alignment frequencies	4	3
	brief notes	67	7
	description	55	20
	gain, low	28	27
	identification <i>vis a vis</i> 670	49	20
	magic eye	16	1
	not working	32	14
		33	33
	repair and cleaning	12	9
		20	10
	resistor fault	14	11
	switch, on/off, faulty	14	12
	valve		
	cap wiring	17	5
	ECC82 replacing EF39	25	21
	/B, testimonial, Tanganyika	59	24
659/670	bearings, seized	88	20
	hybrid model	49	20
	discussion as to identity (Ted Moore)	80	31
	eBay	86	39
		88	25
	p.s.u. details	90	30
	query as to existence of	17	15
	testimonial		
	Invercargill	57	34
	S.S. Ranheim	59	24
670	alignment frequencies	4	3
	battery powered	41	25
	bfo, fitting	17	12
		26	28
	brief notes (Bert Swanley)	15	14
	condenser, leaky	73	9
	coils, long wave, fitted	32	15
	dial light failure	22	18
	distortion, reduction of	29	13
	drifting	16	5
	dropper resistor, corrosion	33	20
	faults, common	17	6
	frequency coverage, gap in	16	3
	featured receiver	4	8
	hum	12	14
		32	15
	identification <i>vis a vis</i> 659	49	20
	Merchant Navy, popular with	82	39
	Mimco equivalent	79	15
	differences	43	28
	modifications, found on set	21	18
	Montreal, used in	55	39
	overhaul	10	21
	phasing control improvement	84	20
	p.s.u. details	90	31
	rectifier, substitute	21	8
	Seafarers' Receiver	28	28
	testimonial	75	15
	British West Indies	57	34
	M.V. British Bombardier	59	24
	M.V. La Pampa	55	39

670 (cont)		
	57.....34
tuning, backlash.....		8.....17
valves		
heater short.....		83.....18
substitutes.....		7.....1
.....		22.....18
UAF42 in lieu of UAF41.....		43.....10
670/1		
Mimco 2232B.....		5.....2
frequency coverage compared with Marconi variants.....		76.....16
heater chain problem.....		74.....15
low gain cured.....		74.....10
670A		
avc not working.....		9.....12
audio, low.....		48.....24
condenser problems.....		50.....36
dial lights		
fitting of.....		22.....5
lack of.....		23.....20
drive cord comments.....		95.....19
early model acquired.....		42.....26
electric shock.....		62.....30
fan, fitting.....		9.....8
faults, common.....		6.....9
.....		17.....6
featured receiver.....		33.....5
ferrite core, loose.....		27.....22
Gulf war, monitoring of.....		32.....17
hum.....		4.....4
hybrid set.....		44.....24
magic eye		
improvements.....		96.....22
restored to life.....		72.....14
mains		
switch, faulty.....		56.....5
voltage, using down to 80v.....		23.....11
Marconi variants.....		9.....7
comparison.....		45.....30
.....		79.....12
.....		96.....36
modifications.....		20.....5
per Short Wave Magazine.....		34.....11
overheating.....		8.....2
rebuilding.....		9.....9
after transistor conversion (!).....		15.....11
repairs.....		33.....14
sensitivity, low.....		6.....3
selectivity, poor.....		5.....3
thermistor.....		6.....9
tuning, vernier scraping dial.....		89.....29
valve sockets, dirty.....		33.....20
valves, new fitted.....		59.....4
670/670A hybrid.....		93.....16
670C		
a.c. only conversion.....		27.....7
.....		35.....17
.....		36.....35
acquired by Graeme Wormald (at last!).....		76.....6
acquired by Ted Moore.....		75.....7
.....		90.....28
aerial input ohms.....		34.....2
audio fault cured, Graeme Wormald.....		77.....11

670C (cont)		
bfo, fitting	27	7
faults, common	17	6
fault on one band.....	74	20
featured receiver	27	5
hum, curing	19	6
knobs, size of	16	15
magic eye improvements	96	22
Marconi variants	96	36
Merchant Navy, popular with.....	82	39
originality	34	10
p.s.u. details	90	31
restoration (Marconi version).....	64	47
rf gain, noisy	13	12
tape recorder output	26	18
C/1		
MIMCO 2232B.....	57	9
680		
acquired by Simon Robinson	62	36
advert	14	18
.....	29	5
Norway	44	10
Stratton & Co Ltd (1949)	77	6
aerial fault cured, Graeme Wormald	77	11
.....	77	31
alignment frequencies	4	3
audio amplifier, use as	45	3
bass, lack of	33	20
Belgian Congo, used in	55	39
bfo, fault	33	8
customised version.....	24	18
differences between early & late models	25	12
.....	29	27
drift	12	14
.....	74	15
featured receiver	29	3
history of one from new (Ellis Taylor).....	14	18
knob variations	62	7
.....	64	63
N.Z. models	12	22
.....	14	4
.....	29	11
owned from new, Jim Daniels (NZ)	77	5
photo & brief description.....	66	38
review		
(GOOGN).....	67	21
Wireless World 1949	67	22
selectivity, superiority over 940	43	28
ssb reception mod.	32	21
testimonial, Iraq Port Directorate.....	57	34
transformer rewind	50	29
tuning scale, backlash.....	33	20
variable bandwidth system	34	14
wiring, incorrect, early sets.....	62	9
680X		
acquisition & repair (Graeme Wormald).....	70	54
advert	62	31
aerials	35	18
bfo, improving.....	28	19
crystal calibrator, fitting within	28	8
drifting	6	3
.....	48	23
eBay	90	17
faults, common	6	11

680X (cont)

featured receiver	5.....7	53.....16
HMS Narvik, seen on	62.....31	
hum, curing	73.....10	
India, faulty consignment sent.....	87.....9	
microphony	82.....44	
N.Z., used for monitoring, later restored	37.....23	
noise limiter, fault	89.....10	
purchased by member, Cornwall	51.....22	
renovation	54.....7	
(Roger Bebbington)	79.....23	
resistor, faulty	22.....6	
A. Africa, in use (Barry Jackson).....	85.....31	
S meter, fault	29.....14	
.....	42.....21	
scale plate cleaning.....	79.....23	
selectivity	11.....10	
.....	43.....30	
switches		
toggle	29.....9	
mains	40.....2	
testimonial		
New York State	55.....39	
Toronto.....	57.....34	
transformer, mains, burnout	24.....16	
valve holder problem.....	58.....8	
variable bandwidth system.....	34.....14	
variants	57.....9	
700		
advert (IMRC).....	70.....31	
blueprint found, Queens model	38.....12	
brief description	24.....9	
boardroom, built for, by Stan Carney	70.....30	
featured model	49.....14	
ferry, in use on.....	43.....30	
history	92.....16	
owned by members	51.....30	
pictures of, shipboard.....	78.....40	
query <i>vis a vis</i> IMR54.....	56.....12	
R.M.S. Queen Mary		
used on	55.....37	
story of	70.....28	
schematic, reference to	51.....5	
710 – see <i>All World Six</i>		
720- see also <i>EY11</i>		
advert, factory.....	61.....1	61.....21
audio response		
curve	39.....15	
graph	39.....16	
brief description	34.....26	
discovered at factory	39.....19	
featured model	61.....21	
Jersey museum.....	89.....19	
parts list, obtained	39.....1	
yacht, in use on	63.....18	
Yachtsman variant.....	21.....17	
.....	53.....1	
developed from 710	61.....21	
730		
advert	4.....11	
CCF, used by	93.....10	

730 (cont)

colours	51	31
crystal calibrator		
weak	8	19
fault	22	18
dismantling & transporting (DWS version ?)	44	4
eBay		
/1A	93	26
/4	93	26
fault finding	40	28
featured receiver	17	8
fuses	84	36
h.t. tracking (burning smell)	50	36
hum	8	19
i.f alignment	60	18
joints, soldered, corroded	55	33
modifications, reversible	35	12
most prolific model	17	18
noise limiter, incorrectly wired from new	30	24
oscillating, a.f. stage	41	19
power transformer disaster	84	42
product detector mod	18	18
.....	19	12
.....	29	19
.....	48	4
Radio Bygones, featured in	28	1
repainting	46	28
resistors, faulty	2	6
.....	59	25
r.f. amplifier mod	35	17
scale plate, cleaning	79	23
Short Wave Magazine, featured in	28	7
switch		
crystal	17	3
mains, failure & replacement	14	18
.....	42	15
replacing	34	14
testimonial, BBC	57	34
tuning system, cleaning	56	2
valves, replacing	10	18
variable bandwidth system	34	14
variants of models	17	12
/1A Diplomatic Wireless Service collapsible model	65	12
restoration of (Roger Bebbington)	70	4
/4		
acquired, Ted Moore	85	23
CCF, used by	89	6
circuit mod	64	54
co-ax connectors available	70	43
comparison with /10 version	63	35
crystal calibrator problem	85	19
diodes, germanium, fitted, query as to	63	6
good points	88	12
in use, EUG net	88	12
polychromatic brown version	56	12
product detector, solid state	62	28
pcb for above mod	63	15
Wireless for the Warrior	89	36
/5 , brief description	18	12
/6 , digital readout mod	14	9
.....	58	17
/10 comparison with /4	63	35
newly acquired set	64	53

740

aerial impedance, importance of	59	6
a.f coupling fault	23	17
alignment frequencies	4	3
auxiliary supply plug	10	14
Braille model (Howard Turner)	43	6
Civil Defence set saved from skip	72	12
crystal calibrator, fitting of	27	10
Elbe barge, used on	21	13
emission, loss of	12	18
faults, common	6	10
fault, factory, cured	76	7
featured receiver	3	5
HT, lack of	7	5
hum, curing	74	17
in use many years	74	15
motorboating	26	2
octal plug on rear	12	13
.....	28	30
output, lack of	32	14
overhaul	7	4
.....	8	7
.....	15	9
p.s.u., type S687	88	20
Q Fiver, use with	27	3
.....	29	15
repairs & mods	33	17
.....	46	4
restoration & purchase (Peter Lankshear)	43	41
S meter fitted	51	30
testimonial, Australia	59	24
transformer, mains, protection of	29	13
valves, blown	35	11

750

acquired by David Fletcher	86	28
advert, Norway	44	10
alignment frequencies	4	3
audio		
capacitor, faulty	55	20
output, loss of	53	2
bfo		
noisy	8	14
lack of	10	15
Buenos Aires owner	21	13
case renovation	9	11
circuit diagram incorrect	31	1
comments on (Chris Pettit)	57	0
current feedback	26	14
design fault query	58	8
doublet aerial described in Marconi HR100 manual	79	32
earth connection problem	22	18
eBay	93	26
faults, common	6	10
favourite model (Terry Parker) details, test results	94	21
featured receiver	12	19
.....	57	21
gain, low	12	14
hum, curing	42	21
.....	76	17
i.f. frequency	51	3
explained	72	42
instability at full volume	7	6
launch date	16	17

750 (cont)

Marconi HR100, equivalent of 750/2	19	18
microphony	12	14
mixer valve	61	7
modifications reversed	59	5
octal plug missing	65	7
output stage description	28	29
resistor (not!)	90	25
valve	91	6
overhaul	8	17
overheating	8	3
product detector, fitting of	29	19
pulley replacement query	79	16
realignment	4	3
.....	18	9
tape recording outlet	22	17
restoration		
Pete Roberts	48	3
Roger Bebbington	72	42
review, 'The Radio Amateur', 1952	58	9
S meter		
fitted	49	27
to make	57	23
scale plate cleaning	79	23
testimonial	94	28
transformer, mains	8	2
tuning gangs, cleaning	52	20
tuning ratio	12	1
twin sets purchased by member	66	6
valves		
C85 fitted to early sets	62	32
substitution, 6AQ5 to replace N78	26	14
.....	34	28
vibrator psu	94	27
voltage stabiliser	10	16
750A de luxe model		
overhaul of	8	11
query as to existence of	16	13
.....	17	12
.....	20	3
750/2 version	19	18
.....	95	18
differences <i>vis a vis</i> Marconi HR100	49	31
MIMCO 2232 equivalent	50	39
760		
new model discovered ?	82	13
.....	82	46
listed by factory	94	49
770CE		
vlf to uhf receive unit	76	17
770M		
brief description	20	3
.....	24	9
.....	26	24
production, low volume	63	33
770R		
advert	2	4
.....	50	35
aerials	7	8
.....	10	8
.....	11	5
.....	46	7
correct type vital	84	16
Dressler active antenna	26	19
links	74	34

770R (cont)

BBC, used by	75	11
Brazil & China, supplied to	42	30
Cumbrian News Group, used by	77	19
deafness, use of pre-amp	61	27
drive cord	6	9
.....	61	28
eBay	92	19
faults, common	6	10
featured receiver	9	19
f.m. fault	26	4
gain, low	14	12
.....	33	13
General Electric (USA), used by	44	21
HMS Collingwood, aboard.....	86	10
MoD designation	33	22
.....	35	14
.....	38	29
NASA, used by	42	1
.....	42	8
original users	2	4
panadaptors, use with	6	7
.....	33	31
.....	45	30
performance, improving.....	78	12
plug, correct type.....	34	21
radio astronomy, used for (Jack Read).....	39	33
repairs	14	14
repairs to Mk II.....	75	6
restoration, major	60	9
rustling cured.....	65	37
.....	74	9
S meter, faulty	22	7
.....	22	16
satellite reception	32	18
sensitivity, low	7	6
.....	8	6
signals, reception of	14	10
solar noise, recording of.....	9	4
tuning indicator, faulty	22	2
Turkish version	57	7
.....	58	5
.....	58	33
turret tuner, reason for.....	14	10
unusual variant	45	13
valves		
replacement (V1, 2 & 3)	24	16
in wrong places	79	12
versions	4	4
/II		
daily usage	71	14
improving performance (Brain Cauthery).....	59	15
plugs, shorting.....	57	25
.....	58	5
.....	58	33
.....	60	19
receiving satellites.....	50	33
used by RAF & RN.....	58	6
used in 2 metre station.....	51	23
830, use in conjunction with.....	60	5
/9 , used by Diplomatic Wireless Service	4	4

770S

Air Ministry numbering.....	5	11
brief description	4	4
.....	10	11

770S (cont)		
	24	8
	32	4
and picture	96	36
designer's comments	24	9
output, lack of	24	8
signals, lack of	27	1
turret tuners	33	10
valves, cost of	30	17
	30	24
variants	54	12
	67	10
770U		
advert	2	4
	3	4
	11	6
aerials	46	7
coil contact problem, 770U (Brian Cauthery)	77	40
drive cord, replacement & plan	37	3
	48	5
eBay	92	19
faults, common	6	10
featured receiver	48	7
full description and pictures	83	9
hard wired mains, NZ	78	6
original users	2	4
panadaptors, use with	28	20
range lamps, intermittent	12	13
sensitivity, low	7	6
turret tuners	33	10
	36	14
valves, correct type	24	8
variations	33	22
793		
projection model	26	29
800		
television model	26	29
810		
info sought (Ted Moore)	26	30
820		
acquisition & case	20	3
advert, Stratton & Co	51	35
case	16	3
	67	5
co-ax sockets	29	13
condenser omitted from circuit	67	5
documentation, original	34	17
dry joint	73	8
fault repaired	59	6
featured model	66	12
frequency coverage, query as to	56	12
gain, low	22	7
	22	20
featured receiver	20	3
H.T. circuit repair	79	16
in use	28	16
photo	66	1
reliability	27	14
repairs	46	4
	48	27
	53	5
	63	20
	65	6
stereo version query	21	2
transformer failure	72	16

820 (cont)

tuning problem.....	51.....	4
valves		
V5 low operating voltage.....	28.....	30
problem cured.....	74.....	16
upgrades.....	61.....	7

830

Addis Abbaba, used in.....	21.....	14
advert, factory (/7version).....	22.....	4
af gain problems cured.....	80.....	36
bfo, drifting.....	26.....	18
Canadian variants.....	26.....	23
calibrator switch, changing to toggle.....	77.....	26
.....	78.....	5
colours, query as to.....	58.....	17
comparison		
AR88 / CR91A.....	47.....	22
Kenwood R5000.....	62.....	7
condenser		
fault.....	22.....	2
replacement.....	19.....	2
crystal filters.....	56.....	3
fitting.....	9.....	24
crystals.....	17.....	9
diodes, replacement for DD006.....	34.....	17
drifting.....	47.....	16
faults, common.....	6.....	10
.....	55.....	16
faults cured		
.....	66.....	5
Brian Cauthery.....	76.....	22
Graeme Wormald.....	77.....	10
featured receiver.....	55.....	14
fingerplates available.....	72.....	2
government service, query as to.....	58.....	18
HT, lack of, curing.....	76.....	17
knobs		
mismatching.....	73.....	11
cracking.....	80.....	5
mods, by member.....	42.....	16
noise limiter, fault.....	42.....	25
meter end-stopping.....	94.....	51
origins of.....	54.....	11
Piccolo		
filter removed.....	9.....	24
.....	37.....	2
microswitches.....	57.....	11
reception of.....	23.....	15
selectivity switch not connected.....	6.....	5
.....	29.....	14
power supply problem.....	83.....	14
RCAF modification labels.....	80.....	36
RCMP model.....	80.....	36
repairs.....	45.....	29
restored to working order		
Chris Morgan.....	77.....	28
Joe LeKostaj.....	78.....	19
John Gillespie.....	81.....	18
sales brochure reprint.....	77.....	21
sideband fault resolved.....	82.....	30
spares kit.....	80.....	5
transformer		
problems.....	54.....	7
burnt out.....	90.....	10
triple diversity racks.....	32.....	12

830 (cont)

tuning lock	91	12
usage in Canadian Govt. service (David W. Whiting)	79	29
valves, substitutes	7	1
770, use in conjunction with	60	5

/4

acquisition & restoration (Brian Cauthery)	90	10
alignment query.....	64	17
query as to Canadian usage	78	21
purchased in Canada	51	23
renovation (Joe Balogh).....	70	23

/5

frequency jumps, curing.....	70	20
imported from Sweden.....	9	3
STC model	5	2

/6

used with morse printer.....	13	5
------------------------------	----	---

/7

restoration (Graham Gosling)	88	28
superiority.....	7	11

/8

AMTOR & RTTY reception	11	13
Diplomatic Wireless Service	1	3
models released.....	96	36

/9

bandwidth conversion (Jim Duckworth)	67	37
case, different size	43	2
co-ax fault & replacement	49	5
local oscillator switch.....	33	29
models released.....	96	36
not working.....	51	5
Piccolo, use with	43	2
.....	65	35
.....	66	28
servicing (Jim Duckworth).....	67	37
synthesizer, use with.....	43	2
/11 STC model	5	2

/12

description & Hagenuck 81 equivalent.....	51	31
frequency coverage.....	19	11

840

advert

factory	46	31
Webb's radio	42	4

bfo

intermittent, curing.....	74	18
modification	15	13

Braille set

.....	44	17
.....	86	26

description

.....	75	15
-------	----	----

dropper resistor

corrosion	27	29
substitute for.....	46	21

eBay, Braille model

.....	86	26
-------	----	----

faults, common

.....	17	6
-------	----	---

featured receiver

.....	26	9
-------	----	---

hum, curing

.....	14	11
.....	29	8

i.f. transformers, query as to.....

.....	70	20
-------	----	----

in use with member 20 years

.....	59	8
-------	----	---

live chassis

.....	15	13
-------	----	----

local oscillator, fault

.....	26	17
-------	----	----

mains voltage, fluctuations

.....	48	28
-------	----	----

power supply details.....

.....	90	31
-------	----	----

range switch

.....	15	13
-------	----	----

840 (cont)

rustling, cured.....	72.....	17
ssb, resolving	15.....	13
transformer 110v	15.....	13
waveband markings	15.....	13
840 II prototype	10.....	15
840A		
AC only modification.....	25.....	14
aerial link, A2 to E	7.....	1
.....	79.....	12
a.f.		
driver stage, fault & cure	58.....	27
gain, not fully operational	36.....	35
audio distortion	7.....	5
avc		
improvement	10.....	18
problems	48.....	10
Brimistor & new bulbs.....	56.....	5
dial light	4.....	4
disabled listener, donated to (by Phil Johnstone)	28.....	10
Dr No, used in film.....	33.....	26
drive cord, restringing.....	25.....	17
dropper resistor	12.....	13
.....	26.....	12
faults, common	6.....	10
.....	17.....	6
featured receiver	1.....	7
gain, low, curing	20.....	15
.....	39.....	17
headphones usage fault.....	10.....	15
.....	14.....	11
h.t. increase, mod.....	33.....	10
hum	10.....	16
i.f. transformer problem	52.....	19
instability on strong signals	27.....	25
magic eye, problems resolved	67.....	4
noise limiter diodes.....	34.....	21
overseas use (Christopher Wood)	39.....	32
power supply details.....	90.....	31
range switch	12.....	8
repairs		
.....	5.....	3
over 43 years	63.....	52
restoration	10.....	12
.....	25.....	19
.....	30.....	11
.....	70.....	22
r.f. & oscillator realignment.....	2.....	2
shipboard use.....	33.....	21
special variant	60.....	7
superiority over Sangean	29.....	1
thermistor problem	86.....	21
transformer, isolation		
110v	61.....	33
fitting of.....	32.....	6
tried out by member	59.....	12
valves		
failure	15.....	2
query as to bases.....	51.....	29
UY41 bypass.....	35.....	20
840C, comparison with.....	64.....	8
840C		
acquired by Ted Moore	75.....	8
advertisement.....	4.....	11
.....	7.....	15

840C (cont)

	48	20
	52	31
	95	40
	95	41
aerial, importance of correct impedance	41	5
agc poor, cured	51	24
a.m., used on net	83	33
bfo, rustling noise at zero beat	10	9
	29	17
case, live	54	3
dial illumination	54	28
drive cord	11	5
dropper resistor, faulty connection	56	5
eBay		
	86	2
	90	17
	94	14
fan, fitting	9	8
fault		
common	17	6
intermittent	29	9
filter, parallel tuned	43	10
featured receiver	7	8
frequency shifting	28	20
i.f. regeneration mod	32	31
l.f. performance poor	52	4
magic eye fault	12	13
	26	20
	80	26
mains wrongly wired	95	22
motorboating	32	21
oscillating	42	31
power supply details	90	31
refurbishing (Peter Beardsmore)	74	28
repairs	65	25
resistors, explanation of	11	9
r.f./i.f. gain, combined control	11	5
S meter adaptation	47	31
sensitivity, low	4	5
spurious signals	35	2
stability	95	19
valve holder problem	82	15
940A, comparison with	64	8
840 II prototype	10	1
850		
broadcast breakthrough	33	9
component values	44	16
condenser, electrolytic, failure	26	4
earthquake prediction	21	2
elf & vlf reception, used for	32	19
featured receiver	39	3
NDB reception	21	16
rack mounted pair, teleprinting	45	8
850/4		
aerials for use with	61	34
gain, low, curing	61	8
manual, errors in	37	8
	48	22
	49	27
repairs	49	16

870

advert	52	15
Strattons.....	59	33
Antarctic, used in (Peter Chisholm).....	59	32
bfo, fitting of	17	12
brief description	30	7
choke, burnt out.....	22	5
condenser, faulty	14	11
deafness, possible causes	67	10
fault, elusive	66	7
featured receiver	24	3
full specifications	84	30
IF core problem	83	19
i.f. rejection circuit.....	16	15
mobile use (Austin A40)	23	20
models acquired (Ted Moore)	79	15
modifications, factory, late models	40	26
owned by US member.....	48	4
overheating, rectifier.....	8	3
prototype found ?	66	8
reception, improving	49	3
restoration	22	13
.....	24	7
.....	25	9
.....	46	19
.....	47	16
Dick King.....	41	9
after transistor conversion	23	11
Roger Bebbington.....	82	10i
scale reversed on these models	75	10
signals, lack of.....	14	12
transistor conversion, inferiority of	25	14
valves		
number, early sets.....	50	31
rectifier, failure.....	47	3
used	25	18
comments on (Ross Paton)	91	7
19AQ5 valve, discussion (Peter Lankshear).....	92	36

870A

acquired (Ted Moore).....	70	17
advert	52	31
audio, distorted.....	35	13
brief description	30	7
broadcast reception, transatlantic	34	11
condenser, electrolytic, failure of.....	42	10
drifting, cured.....	90	24
dropper resistor, replaced by transformer	56	5
eBay	93	26
.....	86	26
.....	86	39
.....	90	16
fault, intermittent (dry joint).....	13	4
featured receiver	36	25
in use	40	17
.....	62	8
isolation transformer mod.....	71	13
modifications		
mains transformer	88	59
to improve (Andy).....	41	3
output transformer, substitute.....	21	8
power supply details.....	90	32
QRM, eliminates.....	90	21
realignment, aerial tuning stage	12	13
receiving ssb signals	74	11
rejuvenated by Ted Moore	76	11

870A (cont)		
reliability & general comments	46.....	1
resistors replaced	53.....	12
restoration	7.....	7
.....	29.....	9
.....	41.....	27
selectivity improvement mod	31.....	22
ssb reception mod	32.....	7
valve failure	94.....	44
.....	94.....	48
WVS, obtained from	28.....	10
880		
acquired by Ted Moore, with picture	76.....	9
bands, loss of	27.....	28
calibrator, fault query	38.....	21
eBay	94.....	13
fault finding	63.....	19
gain, low	4.....	6
.....	29.....	13
GCHQ, used by	92.....	33
greater recognition deserved.....	44.....	4
list of faults, etc.....	82.....	19
local oscillator, comments	71.....	8
noise level	17.....	15
output, low on ssb/cw	42.....	29
product detector fault.....	76.....	16
restoration		
F6EFM	44.....	15
.....	65.....	17
.....	82.....	11
signal jumping	12.....	8
speaker repairs.....	49.....	27
tuning mechanism problems	91.....	5
/2		
advert	52.....	31
featured receiver	46.....	5
picture	47.....	9
speaker repairs	49.....	27
/3		
brief description.....	45.....	22
manual available	45.....	22
.....	46.....	1
Marconi H2301/01.....	9.....	24
.....	46.....	1
/4		
differences between /2.....	48.....	21
881		
brief description	57.....	9
888		
agc, ineffective	5.....	10
avc problems	67.....	6
brochure reprint.....	96.....	18
Bill Cooke, comments.....	96.....	19
crystal calibrator		
repair	33.....	14
.....	48.....	11
.....	65.....	7
.....	73.....	10
tuning	74.....	16
Dr No, used in film (not ?)	32.....	4
drifting	5.....	10
.....	41.....	12
faults, various	46.....	2
fuse blowing, cured	74.....	18

888 (cont)		
in use		
S.Africa (Barry Jackson)	85	31
worldwide	27	1
mains switch, fault	34	4
output transformer faults	61	10
overhaul	22	13
product detector	63	15
repairs	13	10
.....	62	31
ssb reception, improving	59	13
stability problems when new	89	46
tracking, incorrect	27	25
whistles, curing	61	7
888A, difference between	4	4
.....	8	9
.....	87	11
888A		
advert	52	31
.....	84	27
.....	84	29
aerial trimmer	21	8
audio output, complex problem resolved (Graeme Wormald)	90	36
bandspreading	16	16
calibrator, trimming	23	8
case without lid, query as to	46	21
co-ax problems	83	20
condenser fault	14	12
crystal calibrator	54	4
drifting	79	41
possible solutions	80	37
eBay	87	31
.....	94	15
faults, common	6	11
featured receiver	23	2
output, lack of	14	11
.....	26	15
.....	29	14
repairs	56	30
resistor fault	14	11
restoration	23	5
(Ted Moore)	82	12
spurious signals	11	9
ssb reception	22	16
testimonial (Herb Bartlett, G5QA)	84	29
tuning cog repair	63	15
voltage stabiliser	8	4
888, difference between	4	4
.....	8	9
.....	87	11
890		
brief description	10	15
.....	24	10
.....	31	22
discussion of	35	27
900		
c.w. transmitter, mobile, prototype	67	12
909		
acquired from Sweden by member (Anthony Richards)	89	7
power supply details	90	32
brief description	20	12
diode replacement	42	2
featured receiver	31	1
hum, curing	46	2

909 (cont)		
	p.s.u.	18..... 1
	quest for & acquisition (Anthony Richards)	59..... 9
	restoration	54..... 2
910		
	equivalent of Marconi HR101	26..... 13
	79..... 15
	featured receiver	37..... 5
	similarities to 830.....	55..... 33
912		
	brief description	10..... 15
930		
	acquired by Simon Robinson	76..... 44
	discussion of.....	35..... 27
	featured receiver	51..... 6
	model variants	49..... 32
	usage of, new	17..... 7
	Wireless for thw Warrior, included in.....	89..... 36
	/12	51..... 3
935		
	prototype of 940	10..... 15
940		
	acquired by member (David Fletcher).....	86..... 28
	advertisement.....	32..... 26
	34..... 24
	(Webb's Radio, 1962).....	78..... 24
	95..... 40
	95..... 41
	a.f. gain pot failure.....	24..... 2
	AFVs, used in	51..... 4
	alignment, sweep generator.....	72..... 35
	audio	
	crackle.....	25..... 14
	gain increase mod.....	31..... 9
	output distorted	13..... 6
	29..... 10
	19..... 17
	24..... 2
	avc	
	fault cured	58..... 25
	poor	24..... 2
	bfo 'popping'	19..... 5
	bulbs	4..... 2
	cathode vaults low	10..... 14
	cascode problems resolved.....	78..... 42
	coil former fault found.....	73..... 4
	ceramic filters, fitting of (not!)	33..... 4
	comparison, Realistic DX394	70..... 17
	component failure	49..... 28
	condenser	
	electrolytic, failure	18..... 10
	overheating	8..... 19
	crystal calibrator, modifying for	7..... 2
	7..... 13
	24..... 17
	26..... 1
	deafness	32..... 22
	cured	72..... 13
	development history	95..... 39
	dial light mod	24..... 2
	drift & heating problems	79..... 34..
	early sets, differences	45..... 3
	47..... 19
	46..... 3

940 (cont)

eBay	86	26
	94	13
	88	23
faults		
common	6	11
finding	62	40
one member's set	7	5
featured receiver	2	7
fuses, terminals corroded	41	13
gain, lack of	30	5
	52	29
h.f. suffix model	29	11
	32	5
	71	11
history of one set (Peter Lankshear)	70	6
improvements suggested (G8POO)	75	40
comments on foregoing improvements		
G8POO	78	24
Peter Lankshear	76	32
Ross Paton	78	6
instability problems	77	42
in-depth article with graphs (Graeme Wormald)	78	27
comments on, Terry Parker (Eddystone Chief of Test)	78	34
in use		
G.E.W. Hewlett	56	13
Ray Howgego	56	13
microphony	18	8
MoD version	31	1
origins of	79	35
output, lack of	15	2
output transformer, substitute	21	8
phone jack, oxidation	86	22
purchased in Scotland (Brian Abrams)	50	26
	52	33
ranges not working	77	14
refurbishment		
Graham Sutton	92	13
Ted Moore	71	12
repairs	48	16
	60	38
notes (Roger Bebbington)	68	39
resistors		
high	8	19
burnt out	10	16
problems	23	7
	74	14
replacement	25	18
	29	10
	64	63
restoration	14	15
Geoff King	56	18
S meter problems	54	5
selectivity, poorer than 680	43	28
sensitivity, lack of	17	6
servicing	12	16
(Graham Leese)	12	25
specifications & info	85	12
squelch fitted	8	9
	12	12
stenode modification	56	12
taken to school (Ted Moore)	74	8
transformer, winding	12	14

940 (cont)		
tuning		
mechanism	26	2
ratio	12	1
valve seating problem	63	35
variants	54	13
/1		
Variant with crystal controlled channels added	79	14
950		
valved radio to cope with EMP	93	32
958		
advert	15	18
assessment, School of Signals (1977)	94	6
bulbs, query as to voltage	77	20
catalogue extract	49	9
comparison, different versions	8	13
co-ax, coupling, corrosion	26	11
.....	27	2
.....	37	11
.....	38	2
eBay	91	21
faults	38	9
.....	67	31
featured receiver	14	6
Hagenuk & Marconi equivalents	79	15
intermittent function	33	19
Isle of Wight museum	26	19
manuals available	47	30
maritime radio, used by	94	9
MoD reference numbers	20	12
overhaul	12	15
.....	35	3
prices	24	17
restoration (Graham Gosling)	88	28
scale cursor query	57	10
problem cured	58	18
servicing	17	13
success of	44	5
suffix, query as to	47	17
tuning		
ratio arm, setting	56	17
display, fault	12	13
/H , Hagenuk version	5	2
/D , Debeg version	5	2
/1 , P.O. acquires 50 sets	85	43
/4 , MIMCO H2310 equivalent	54	13
/5		
MIMCO Nebula	52	12
manual	19	11
/7E		
featured model	67	17
first with digital readout	46	6
960		
acquired by Ted Moore, restoration begun	86	28
.....	88	14
.....	90	22
advert, Strattons	54	23
battery operation, nicads	38	9
brief description	18	12
.....	29	18
bfo problems	10	16
.....	13	15
eBay	89	9
featured receiver	16	10
i.f. rejector tuning	10	16

960 (cont)		
	retrimming after transistor change	9..... 11
	solar powered.....	8..... 6
	transistor, r.f., blown	10..... 16
	variations, later sets	32..... 22
	940, comparison with	9..... 7
	26..... 29
961	info sought	39..... 19
964	acquired by Ted Moore	85..... 23
	catalogue extract	49..... 9
	monitoring, used for, N. Sea oil.....	86..... 21
990R	advert, factory.....	36..... 31
	aerials, suggested	20..... 8
	brief description	9..... 8
	36..... 31
	catalogue extract	49..... 9
	crystal units	37..... 9
	deafness, use of pre-amp.....	61..... 27
	drifting	42..... 23
	drive cord comments	95..... 19
	drop testing, factory.....	60..... 37
	eBay	94..... 14
	fault finding (Geoff Harris)	93..... 38
	faults, common	17..... 5
	frequency deviation, figures sought	36..... 14
	gliding club, in use at.....	55..... 5
	i.f. convertor circuit	40..... 14
	layout differences	95..... 23
	Met Office usage	61..... 40
	microphony	89..... 22
	muting switch repair	62..... 11
	non working	12..... 4
	portable use	88..... 21
	prices	
	secondhand.....	27..... 23
	1982	62..... 6
	publicity at launch.....	62..... 34
	reception	61..... 27
	review, Short Wave Magazine	64..... 21
	scale calibration.....	94..... 28
	tuning gear problems.....	89..... 27
	variations	90..... 27
990S	advert, factory.....	20..... 13
	36..... 32
	faults, common	17..... 5
	drive cord comments	95..... 19
	eBay	94..... 14
	featured receiver	8..... 7
	mystery variant (Louis Muelstee)	96..... 24
	production figures.....	54..... 15
	scale calibration.....	94..... 28
1000	featured receiver	25..... 6
	toggle switches, new	56..... 5
1001	catalogue extract.....	49..... 9
	eBay	91..... 20
1002	bfo not fitted	63..... 13
	brief description	14..... 1
	catalogue extract.....	49..... 9

1002 (cont)		
eBay	95	28
	95	29
HMS Collingwood, aboard	86	10
front panel replacement	77	14
IC, equivalent of TAA300 query	46	13
lack of AVC, cured	94	44
noise		
curing	43	24
level, high	61	11
problems	86	17
rack mounting – not !	49	27
restoration (Ted Moore)	70	37
tuning, problems	70	18
variants: Marconi, Hagenuk, Redifon, ITT	61	11
1004		
bfo fault	26	27
catalogue extract	49	9
description & picture	80	43
eBay	95	28
1004		
fault repaired	49	3
Hagenuk E92	5	2
	79	15
ITT version	5	2
MIMCO Sentinel	5	2
Redifon version	5	2
1529		
RTTY terminal	96	34
1560		
ROM missing	93	19
/R2		
Marconi Marlin	86	19
query as to model designation	85	22
1570		
featured receiver	35	7
owned by Chris Pettit	64	3
pcb	20	3
poor sets advertised, acquired (Ted Moore)	81	39
1590		
board ref. nos.	19	5
1610		
brief description	71	34
1650		
brochures, reference to	49	21
designer, in EUG	60	6
eBay	91	19
featured model	58	19
GCHQ sets, conversion of (Geoff Steadman)	72	6
loss of by factory	56	2
	59	26
Operation Raleigh, used by	58	2
pcb	20	3
pros & cons (Michael O'Beirne)	61	29
response by designer, Roger Sutton	61	31
submarines, use with	66	3
supplied to STC	81	4
/6		
on surplus market	45	0
caution when buying	45	5
	46	1
	47	30
1705 transmitter		
vhf broadcast tx	62	3

1706 transmitter		
sold on eBay.....	91.....	19
1806/2		
handset amplifier, query as to	67.....	2
1810		
brief details	48.....	26
1830		
advert, factory.....	53.....	14
German version.....	48.....	26
/ICE suffix, query as to	54.....	16
1837		
availability secondhand	33.....	21
capacitor problem, common	64.....	7
faultfinding & notes (Gary Donovan)	62.....	4
featured receiver	60.....	13
Marconi Pacific.....	26.....	1
press release, Sept 1977	16.....	14
/1, usb only	61.....	7
1838		
comparison, FRG100	62.....	7
1940/1		
featured receiver	53.....	9
info. sought	83.....	21
sent to Marconi for evaluation	79.....	15
1964		
ex trawler, purchased by member	42.....	18
1990R		
acquired by Ted Moore, with picture	76.....	10
.....	85.....	23
catalogue extract.....	49.....	9
fault, cutting out, curing	76.....	14
HMS Collingwood, aboard.....	86.....	10
picture & description of station	45.....	2
.....	45.....	6
problems resolved (Alan Robinson)	87.....	32
tuner damaged by static ?	82.....	17
used on MILAIR frequencies	79.....	17
use with Panadaptor, HMS Euralyus	24.....	10
1995		
brief description	12.....	8
2004		
brief description	24.....	18
2232A (Marconi)		
capacitor failure	94.....	44
2245A (Marconi)		
670A equivalent acquired (ted Moore)	94.....	48
2273A (Marconi)		
fault cured	93.....	18
frequency coverage.....	96.....	36
3873A (Marconi)		
P.A. built in	96.....	36
6100		
brief mention, Chris Pettit.....	63.....	3
joys & pitfalls of ownership (Dave Jones, MW1DUJ)	91.....	25
6200		
available at discount.....	73.....	24
brief description	41.....	32
brief mention, Chris Pettit.....	63.....	3
continues in production	55.....	35
All Wave Four		
advert, factory.....	38.....	11
.....	65.....	31
development, description & photo.....	65.....	28
photo	65.....	1

All Wave Four (cont)

review, Wireless Magazine, 1931	65	32
used in India, rejuvenated after 50 years	79	6
well travelled, in use many years (Amy O'Neil)	75	22

All World Two

acquisition & description	56	27
adapting for 10 metres	76	1
advert	36	24
.....	44	23
.....	92	30
cost, new	44	27
discussion regarding (Tor Marthinsen) & picture	79	36
eBay & pictures of	92	18
featured receiver	28	25
owned by Davis Fletcher	86	28
restoration	26	25
review		
Wireless World 1936	39	25
Practical & Amateur Wireless 1936	44	2
.....	79	24

All World Four

brief mention	25	4
description, all variants, accessories, etc.	58	37
testimonial, S. Rhodesia	59	24
used in New Guinea & Solomons, WWII	55	39
Wireless World review, reference to	63	14

All World Six

advertisement	95	24
factory, with specification	19	9
Norway	44	10
Africa, use in	24	9
alignment frequencies	4	3
brief description	3	5
.....	10	15
.....	95	25
communal listening model	68	4
discussion on, Tor Marthinsen	80	22
featured receiver	19	15
Nigeria, used in	55	39
owned by Tor Marthinsen	54	18
repairs	33	33
testimonial, Papua New Guinea	59	24
vibrator units		
possible source	48	28
repair	65	10
wind generator, powered by	9	2
710/B	4	4
Yachtsman, developed from	61	21
.....	66	8

All World Eight

advert, factory	34	12
brief description	12	2
.....	12	24
description & photos	64	55
differences, early & late models	24	4
featured receiver	13	16
military use	89	26
owned by member	65	8
R101 version used by R.N.	36	14
.....	64	55
.....	65	16
full description of, & circuit	74	36
info sought & photo	64	55
Wireless for the Warrior, included in	89	36
speaker	67	31

All World Eight		
Stratton & Co, letter from.....	65.....	9
Wireless World, 1936	53.....	23
Amateur Bands Two		
description	71.....	42
& circuit	68.....	16
discussion regarding (Tor Marthinsen).....	79.....	36
first Eddystone receiver ?.....	71.....	24
review	68.....	17
transmitter	67.....	13
Atlantic Two		
acquired in NZ (Brian Marsh)	61.....	10
brief description	33.....	26
.....	34.....	15
sold by Harrods.....	45.....	9
comments and picture	94.....	39
discussion regarding (Tor Marthinsen) & picture	79.....	36
featured model	62.....	14
photo	62.....	1
reception, transatlantic, guaranteed.....	64.....	7
sold at auction	86.....	39
Atlantic Short Wave Two		
'Eddystone specified' construction project	63.....	36
Atlantic Three		
details of	78.....	33
'Eddystone specified' construction project	64.....	50
existence of	38.....	25
Band Spread All Dry Four		
'Eddystone specified' construction project	66.....	32
Colonial		
query as to existence of	36.....	4
Crystal Set		
picture of	92.....	5
ditto plus comments	94.....	37
EA12		
advert, factory.....	32.....	26
.....	48.....	20
avc problems	67.....	32
chirpy cw	29.....	13
cw & ssb mode failure	53.....	20
dioded, caution with.....	60.....	5
eBay	86.....	26
.....	86.....	31
.....	88.....	24
.....	90.....	15
.....	91.....	20
.....	94.....	15
faults	48.....	23
featured receiver	44.....	11
full description and pictures.....	81.....	10
gain, low	7.....	12
on certain bands.....	33.....	20
frequency coverage & stations audible	95.....	16
meter end-stopping	94.....	51
non-standard set	64.....	5
overhaul & rectification of apparent factory faults	21.....	12
peak r.f. control fault.....	14.....	12
power supply section, failure in	42.....	14
product detector, problems with	44.....	13
prices, new	46.....	19
purchased new from G5GX.....	27.....	9
QRP transmitter within	13.....	5
realignment	26.....	19
repairs	49.....	17

EA12 (cont)		
	71.....	13
RSGB HQ, on display.....	22.....	11
	29.....	22
S meter		
	46.....	24
	47.....	22
scale	25.....	13
incorrect readings.....	42.....	31
transistor front end considered.....	25.....	13
using properly.....	27.....	4
variable bandwidth system.....	34.....	14
EB35		
acquired		
at auction.....	66.....	26
Ted Moore.....	87.....	29
aerial		
effect of very long wire.....	34.....	21
vhf	37.....	31
	39.....	19
airband reception.....	33.....	1
audio hiss, curing.....	77.....	33
audio output		
lack of.....	14.....	11
	33.....	19
distorted.....	29.....	14
	36.....	35
battery		
case	9.....	5
	37.....	13
corrosion.....	20.....	6
operation.....	35.....	21
use of PP9.....	56.....	5
bfo, fitting of.....	12.....	10
	16.....	20
brief description.....	96.....	39
bulbs		
query as to voltage.....	77.....	20
replacing with LEDs.....	55.....	27
catalogue extract.....	49.....	9
circuit compared with Mk III.....	67.....	21
diode D1.....	41.....	28
drifting.....	7.....	14
EB37, comparison with.....	30.....	21
Eddystone Lighthouse, presented to.....	11.....	16
faults, common.....	6.....	10
featured receiver.....	11.....	1
f.m. reinstated.....	49.....	4
	63.....	52
headphone socket.....	42.....	7
hiss		
curing.....	25.....	7
unaffected by volume control.....	43.....	27
HRH Prince Charles, fitted to car.....	67.....	21
identifying features, all models.....	40.....	31
i.f.		
mod, controlable.....	18.....	16
coils, substitutes, care as to.....	67.....	8
light switch, mod.....	13.....	6
	16.....	20
loudspeakers.....	17.....	6
mains psu		
danger.....	25.....	7
	66.....	26
description.....	37.....	13

EB35 (cont)

diode replacement.....	34	29
noisy	76	16
plug polarity.....	85	20
Mk II, differences	16	19
.....	22	9
Mk III, differences	8	6
.....	67	21
mobile psu	14	14
modifications corrected	72	16
noise, output stage.....	76	16
noise limiter, fitting of.....	16	19
non working	21	16
pcb no. 75328/W	33	31
Prince Charles, owned by	82	15
restoration	80	32
.....	81	37
.....	82	15
restored to life.....	75	9
selectivity, improving	22	9
.....	37	17
signal, lack of (a.m.)	27	3
stereo version.....	21	2
Toko i.f. coils	68	34
transformers & cores, damaged.....	85	25
BC212 substituted, f.m. section	49	4
replacement	44	9
substituting silicon type (not!).....	34	10
whiskers on	8	11
.....	37	2
transistors, silicon to replace germanium.....	68	35
tuning cord reversed.....	79	12
used overseas.....	21	13
variations	90	27
wavechange switch problems	84	35
zener diode	60	20
noise	50	33
EB35A		
brief description	7	14
differences from standard model.....	96	37
EB35 Mk II		
audio hiss, curing	77	33
identifying features	40	31
i.f coils		
substitutes, care as to	67	8
Toko	68	34
Joint Services / NATO stock no.	13	13
Mk I, differences	16	19
.....	22	9
Mk III, differences	8	6
NATO release of sets.....	41	25
output transistor replacement.....	79	17
psu diodes, replacement	34	29
realignment & overhaul	29	19
restored to life.....	75	5
IIS comparison with II/S.....	44	24
II/S comparison with IIS.....	44	24
EB35 Mk III (Statesman)		
acquired & got working.....	67	6
circuitry, different from earlier models	67	21
featured receiver	34	31
identifying features	40	31
Mk I, differences	8	6
Mk II, differences	16	19

EB35 Mk III (cont)		
	22	9
	67	21
negative earth, warning as to	68	26
price, 1982	62	6
above incorrect, Bill Cooke	63	34
r.f. gain, fitting of	42	22
variants	35	8
EB36		
acquired by Ted Moore	75	5
audio hiss, curing	77	33
advert, factory	9	16
acquisition & refurbishment	42	17
aerial, ferrite, for use with	27	19
batteries, use of PP9	57	3
current consumption, excessive	43	27
identifying features	40	31
i.f. coils, substitutes, care as to	67	8
noisy set cured	74	9
realignment	33	7
Reuters, owned by	38	10
transistors, silicon to replace germanium	68	35
EB36A		
differences between this & EB36	75	38
GPO use, query as to	51	29
EB37		
acquired, Ted Moore	87	29
advert, factory	15	18
aerial, ferrite, for use with	34	11
batteries, use of PP9	57	3
bfo, fitting	27	15
brief description	18	12
ceramic filters, effect of	19	2
comparison with EB35	30	21
featured receiver	50	10
frequency drift, curing	58	26
gain, low	56	2
harmonics, faulty diodes	26	12
identifying features	40	31
i.f. coils		
substitutes, care as to	67	8
Toko	68	34
microphony	18	8
motorboating	14	12
nicads, use of	57	2
output		
distorted	14	12
lack of	18	8
psu diodes, replacement	34	29
realignment considered	29	21
restoration (Chris Morgan)	68	35
solar power	29	25
transistors		
bewhiskered	23	14
silicon to replace germanium	68	35
EC10 (Mk I & Mk II)		
acquisition & recomissioning	63	50
acquired, Ted Moore, query as to new variant	87	28
advert, factory	10	0
	32	26
	48	20
Strattons	54	25
audio hiss, curing	77	33
battery		
case	9	5

EC10 (Mk I & II cont)

	37	13
corrosion	20	6
substitution	23	19
use of PP9	56	5
bfo fault	12	13
	33	19
	39	17
	42	22
bulbs		
replacing with LEDs	55	27
query as to voltage	77	20
ceramic filters	19	2
circuit diagram errata	74	8
condensers, ageing	47	2
cutting out, curing	76	15
comparison with other receivers	16	6
crystal calibrator, fitting	14	13
dial lamps		
module	90	44
substituting LEDs	26	8
diode failure		
D1	28	29
	41	28
lighting, caused by	23	13
drifting	12	13
	33	19
	34	16
	42	13
	61	39
	63	8
eBay	88	24
	90	15
	92	19
	93	25
	95	29
EUG net, used on	88	18
faults, common	6	10
featured receiver	10	3
filter		
problems	29	12
modifying for c.w.	29	13
fine tuning		
control	47	17
fault	17	5
	60	8
Ford Zephyr, fitted to	8	7
Goat Fell, used portable	80	33
Gulf War, monitoring	9	1
hiss		
curing	25	7
unaffected by volume control	43	27
HMS Collingwood, aboard	86	10
identifying features, all models	40	31
i.f. transformers		
cannibalised	56	16
query as to substitute	61	39
replacement effected (Jim Duckworth)	66	15
substitutes, care as to	67	8
Toko units	66	4
instability, curing	59	28
Isle of Arran, in use on	78	16
loudspeakers	17	6
mains psu		
danger	25	7

EC10 (Mk I & II cont)

.....	42	2
.....	66	26
description	37	13
faults	33	18
noisy	76	16
pcb	60	31
MIMCO 6689, equivalent.....	5	2
.....	71	14
.....	79	15
model variations (Tor Marthinsen)	18	17
mods		
corrected	72	16
Tom Toth.....	72	44
noise, output stage	43	27
.....	76	16
output, intermittent	20	16
output transformer replaced	70	14
overseas use	21	13
overloading	43	31
Portugal	89	6
Practical Wireless, owned by	31	11
printed circuit board repairs.....	76	13
production details	61	39
psu		
plug polarity.....	85	20
incorrect	73	5
purchased new		
from Imhofs	37	24
(Roy Elwen).....	38	31
QRM, reducing	9	7
.....	57	4
Radiophile, featured in	47	1
resistors, ageing.....	47	2
resistor failure, cured.....	94	44
r.f. protection	10	11
restoration	27	17
.....	28	13
.....	60	36
S meter problem.....	56	15
scale		
cursor misplaced.....	42	29
markings, comments on (Terry Parker)	94	28
.....	95	23
selectivity, improving	37	17
.....	57	18
servicing	16	6
.....	57	18
Short Wave Magazine, featured in.....	28	7
solar powered.....	6	3
spurious signals.....	36	3
ssb reception	38	31
switches		
push button	40	2
wafers loose	56	4
Toko i.f. coils	68	34
transistors		
failure due to static.....	58	16
faults	73	6
incorrect fitted.....	27	11
replacing.....	44	9
substituting		
BC212 in af stage	44	28
with silicon types (not ?)	26	28

EC10 (Mk I & II cont)		
	34	10
	68	35
OC170 with AFZ11 & AF212	63	8
OC171s with BSX29s	59	2
	61	39
ditto, RCA N2370	64	63
ditto, NKT674 & 2N2907	64	63
	63	8
website on substitution	63	8
whiskers on	8	11
upgrades to modern types	73	6
transmitter incorporated	26	22
variations	90	27
wrong psu supplied	73	5
ZOO-2350 models, query as to	37	1
EC10 Mk III		
brief description	7	11
EC10A/2		
brief description	8	12
diodes, protective	55	22
i.f. frequencies, different	67	8
Short Wave Magazine, owned by	30	14
Sunbeam Rapier, used in	30	22
EC10 Diplomat		
brief details	75	29
EC10M		
acquired by member	54	15
equivalent of Marconi Seaguide, full details	94	9
ECR		
acquired by member	63	51
	77	12
at NVCF, picture of	79	39
Brazil, set discovered	66	6
discussion regarding (Tor Marthinsen)	80	22
mint example bought (Tor Marthinsen)	47	31
	53	11
Edometer		
description	7	11
	24	18
fault	33	19
featured model	42	3
	42	5
EK20		
brief description	11	2
prototype	10	15
query as to	17	7
EM34		
acquired by member (Anthony Richards)	85	8
Marconi Elettra	54	16
Mimco equivalent	79	15
repairs	52	29
Empire Two		
description, circuit & pictures	81	28
discussion regarding (Tor Marthinsen)	79	36
good receiving ability	40	29
ERA		
advert, factory	31	27
	34	12
comparison, ERA 7	32	5
	43	30
discussion regarding (Tor Marthinsen)	80	22
existence, confirmation of	45	8

ERA (cont)		
featured receiver	30	3
Everyman		
advert, factory.....	2	1
.....	34	27
.....	37	21
.....	40	30
.....	41	20
blueprint	49	31
brief description	39	21
.....	45	1
choke, smoothing.....	21	8
comments by Tor Marthinsen.....	77	36
copy brochure.....	78	8
featured receiver	22	3
.....	40	7
improved version	57	12
.....	57	13
manufacture, dates of.....	37	29
manual	34	8
160, Services equivalent	21	9
EY11		
acquired at Leicester Show	63	13
.....	63	18
brief description	24	9
.....	30	19
.....	40	11
discovery at factory	41	27
featured receiver	59	22
further information, prototype	42	9
prototype	55	22
Homelander		
brief details	45	1
featured receiver	45	15
retrieved from loft	11	2
used by Mt. Everest Expedition, plus details & pictures	95	36
Homeland Four		
advert, Stratton & Co.....	63	16
construction booklet available	44	34
factory advert.....	83	25
picture of, at Colchester rally.....	93	24
IMR54 – see 700		
Kilodyne Four		
advert		
factory, Antarctic Expedition	44	7
.....	45	12
.....	47	18
Stratton & Co Ltd, 1931.....	74	24
.....	60	2
reference to.....	61	7
block schematic.....	18	1
comments by Tor Marthinsen.....	77	36
description, circuit, pictures	82	31
featured receiver	18	2
full description, Wireless Magazine 1932.....	74	25
information available (circuits, etc.).....	37	12
partly built set discovered (David Lewis).....	28	7
photos & acquisition	63	34
restoration	96	10
to be built ?		
Ted Moore.....	83	19
Graeme Wormald.....	82	46
Voluntary Interceptors, used by	42	24
KT66		
built for RAF & RN reservists	96	54

L.P.C.		
advert, factory.....	34.....	27
.....	41.....	16
Marconi / MIMCO models		
2232A	94.....	44
2232B	5.....	2
2245A	94.....	48
2273A	93.....	18
.....	96.....	36
3873A	96.....	36
6689	5.....	2
.....	71.....	14
.....	79.....	15
HR100	19.....	18
H2301/01	9.....	24
HR101	26.....	13
Marconi / MIMCO models		
HR101	79.....	15
Pacific	26.....	1
Sentinel	5.....	2
Orion		
acquired & recommissioned (Ted Moore)	85.....	27
.....	86.....	15
brief description	25.....	1
.....	26.....	27
development & marketing, notes on.....	59.....	2
featured model	52.....	12
in use on EUG net	73.....	24
.....	88.....	19
on yacht Esselle.....	90.....	25
production history	65.....	3
QSL card, Eddystone Radio, featured on	88.....	4
sold to Egypt.....	83.....	5
sold on Ebay + picture.....	84.....	5
spares, query as to (Simon Robinson).....	78.....	25
transceiver available at discount	73.....	24
5600/2 version	52.....	21
7000 version.....	34.....	0
production ceases.....	55.....	22
Overseas Four		
acquisition & photos (M5POO).....	66.....	27
Portable Three		
comments	94.....	38
Quadradyne		
comments by Tor Marthinsen.....	77.....	36
Queen Mary - see 700		
Radiosonde receiver		
featured model	56.....	25
RAF CWR Transmitter		
building of, Graeme Wormald.....	48.....	16
featured model	47.....	12
.....	47.....	31
Regional One		
comments	93.....	5
comments	94.....	40
first ever Eddystone.....	61.....	6
R74		
query whether Eddystone.....	18.....	17
R101		
<i>see All World Eight</i>		
R213		
<i>see 770</i>		
S147		
440/450 equivalent, used by R.N.	76.....	15
Scientific Two		
advert for	80.....	12

Scientific Two (cont)		
blueprint available	38.....	29
discovered by member	90.....	26
discussion regarding (Tor Marthinsen) & picture	79.....	36
featured receiver	41.....	10
Scientific Three		
advert	43.....	22
brief description	30.....	19
details of & picture	43.....	22
.....	78.....	32
construction manual, reprint of	64.....	25
query as to details	43.....	10
Scientific Four		
advert	41.....	14
Harrods	64.....	19
broadcast stations, listed in handbook (1927)	36.....	9
circuit description	64.....	18
comments		
by Tor Marthinsen	77.....	36
and picture	94.....	39
construction manual	35.....	23
full description, circuit, pictures	76.....	25
sold at auction	58.....	33
Scientific Five		
comments and picture	94.....	40
details required	61.....	11
Scientific Portable Three		
comments and picture	94.....	41
Scientific Short Wave Three		
comments and picture	94.....	40
construction booklet available	44.....	34
discovery of existence of, Graeme Wormald	43.....	5
Scientific Screened Grid H.F. Short Wave Three		
New model discovered resembling above (Percy Mistry)	91.....	8
Sentinel – see 1004		
Short-Wave		
comments and picture	94.....	39
discussion regarding (Tor Marthinsen)	79.....	36
first Eddystone	96.....	14
Wireless World extract	96.....	15
Short Wave Convertor		
.....	72.....	36
.....	72.....	39
Short Wave Two		
construction of (Martin Lindars & Graeme Wormald)	45.....	32
.....	64.....	20
discussion regarding (Tor Marthinsen)	79.....	36
full description	80.....	13
monitoring, WW II	40.....	33
replica, intention to build	27.....	16
.....	34.....	2
report of set in use, Graeme Wormald	46.....	25
Short Wave Three		
adjustment & operation	61.....	4
circuit	61.....	5
constructors' handbook, reference to	64.....	17
Sphinx		
advert, factory	15.....	0
brief notes	15.....	1
.....	48.....	19
circuit	15.....	20
comments by Tor Marthinsen	77.....	36
discussion regarding (Tor Marthinsen)	80.....	22
featured receiver	15.....	5

Sphinx (cont)		
owned by members	17	18
.....	12	8
restoration, major	48	16
Statesman - see EB35 Mk III		
Stereo 500 (transmitter)	84	21
Super Six		
description & restoration.....	71	15
discussion regarding (Tor Marthinsen).....	80	20
omitted from QRG, but evidence of.....	96	44
'Tardis'		
multi-service f.m. transposer system.....	61	2
Three		
advert	71	24
description of	78	32
comments and picture	94	38
first Eddystone receiver ?.....	71	24
Twin		
acquired (Simon Robinson).....	70	50
blueprint	53	3
brief description	25	21
& photos	70	50
picture of & on display	93	24
comments and picture	94	38
owned by Graeme Wormald.....	30	1
purchased by Graeme Wormald	39	11
replica, intention to build.....	34	2
.....	42	30
sold on eBay & picture of	92	17
Two		
comments and picture	94	38
data sheet found, 1926 model.....	70	11
discussion regarding (Tor Marthinsen).....	79	36
Two Valve Short Wave Receiver		
'Eddystone specified'.....	79	38
Two Valve VHF Transceiver		
'Eddystone specified', not factory built.....	62	38
Ultra Short Wave Radio Telephone		
construction article, advert for	38	13
featured set	38	15
for sale	87	17
Unknown model		
<i>see Scientific Screened Grid H.F. Short Wave Three</i>		
WS57		
Wireless for the Warrior, included in	89	36
440/450 equivalent, used by Army	77	9
XE10 vhf transmitter		
brief description	68	3
.....	64	3
XE15		
stereo exciter.....	68	3
Yachtsman (see also EY11)		
720 variant	21	17